



United States Steel Corporation  
Clairton Works  
400 State Street  
Clairton, PA 15025

June 29, 2004

Dr. Roger C. Westman  
Department of Air Quality  
Bureau of Air Pollution Control  
301 Thirty-Ninth Street  
Pittsburgh, PA 15201

U.S. Environmental Protection Agency  
Region III  
Air, Radiation & Toxics Division  
1650 Arch Street  
Philadelphia, PA 19103-2029  
ATTN: James W. Hagedorn

Assistant Council  
Department of Environmental Protection  
Division  
Southwest Region  
400 Waterfront Drive  
Pittsburgh, PA 15222-4745  
ATTN: Steve Hepler

Department of Justice  
Environmental and Natural Resource  
Environmental Enforcement Section  
P.O. Box 7611  
Ben Franklin Station  
Washington, D.C. 20044  
ATTN: David Street, Esq.

Subject: USS Reference Number: 04-0119  
ACHD Reference Number: 5315  
#8 Battery Igniter Flare  
USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the outage. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

Anton Lukac  
Plant Manager  
Clairton Works

NOTICE OF BREAKDOWN OF EQUIPMENT  
ARTICLE XXI - SECTION 2108.1

1. USS Reference Number: 04-0119  
ACHD Reference Number: 5315
2. Date & Time of Breakdown: Date: 06/28/04 Time: 0900 hours
3. Company Name: U.S. Steel Corporation - USS Clairton Works
4. Specific Equipment Involved or Affected: #8 Battery Igniter Flare
5. BAPC Permit Number (if applicable):
6. Location: Clairton, PA
7. Nature and cause of breakdown: For safety reasons, the #8 Battery Igniter Flare was unavailable for service. Lifts to repair the bunker were being made in close proximity of the flare. There was no environmental impact.
8. Identification of Emissions:
  - A. Type(s) (CO, NOX, SO<sub>2</sub>, Particulates, Hydrocarbons, etc.)  
No environmental impact.
  - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). N/A
  - C. Amount of each type emitted (or likely to be emitted).  
N/A
9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).  
The task was completed and the Igniter Flare was available for service.
10. Facility back in operation - Date: 06/28/04 Time: 1500 hours

Signature Coleen M. Davis Date 7/1/04  
Coleen M. Davis  
Senior Environmental Control Engineer Phone: 233-1015